

Makita Schleif Kohlen CB-419(Cb-406 407)



Bewertung: Noch nicht bewertet

Preis

8,33 €

1-2 Days
★★★★

[Eine Frage zu diesem Produkt stellen](#)

Beschreibung

Makita KOHLEN CB-419(CB-406/407)

- nur noch Restbestand erhältlich!
- Ersatzteilnummer 191962-4
- passend für Modelle
- 4304, 4304T, 4305, 4305T, 4340CT, 4340FCT, 4340T, 4341CT, 4341FCT,
- 4341T, 4350CT, 4350FCT, 4351CT, 4351FCT, 6310, 6408, 6807, 6821, 6823
- 6824, 6824N, 6825, 6825R, 6826, 6826N, 6827, 800, 8450, 8451, 9046, 910,
- BO4555, BO4556, BO4557, BO4565, BO4566, BO4900V, BO4901, BO5000,
- BO5001, BO5030, BO5031, BO6030, DA3010, DA3010F, DA3011, DA3011F
- DP2010, DP2011, DP3003, DP4001, DP4003, DP4010, DP4011, FS2300, FS2700
- FS4000, FS4300, FS6300, FS6300R, HP1620, HP1620F, HP1621, HP1621F, HP1640
- HP1641, HP2030, HP2031, HP2032, HP2033, HP2040, HP2041, HP2050, HP2050F,

- HP2051, HP2051F, HP2070, HP2070F, HP2071, HP2071F, HR1830, HR2020, HR2410
- HR2430, HR2431, HR2432, HR2440, HR2440F, HR2450, HR2450F, HR2450FT, HR2450T
- JR1000FT, JS1300, MT924, UH4260, UH4261, UH4570, UH4860, UH4861,
- UH5260, UH5261, UH5570, UH5580, UH6570, UH6580, UH7580

Produkteinheiten pro Packung: 1 Pkg.